## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,800,140 B2

Page 1 of 1

DATED

: October 5, 2004

INVENTOR(S) : Samuel N. Hansen

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 7,

Line 19, reads "the reed switch 46 is fixed an a location" should read -- the reed switch 46 is fixed on a location --.

## Column 11,

Line 32, reads "to the surface to be" should read -- to the surface to be cleaned; --.

Signed and Sealed this

Sixteenth Day of August, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office